

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:						
OGM	Pete Hess					

Inspection Report

Permit Number:	C0070045		
Inspection Type:	COMPLETE		
Inspection Date:	Thursday, July 08, 2010		
Start Date/Time:	7/8/2010 9:05:00 AM		
End Date/Time:	7/8/2010 10:40:00 AM		
Last Inspection:	Tuesday, June 08, 2010		

Inspector: Pete Hess,

Weather: Sunny, low humidity. 80's F. InspectionID Report Number: 2418

> Accepted by: jhelfric 7/29/2010

Permitee: HEADWATERS ENERGY SERVICES Operator: HEADWATERS ENERGY SERVICES

Site: COVOL SITE

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: PROPOSED Active

Current Acreages

30.00	Total Permitted		
30.00	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Federal State

County Fee

Other

Types of Operations

Underground Surface

☐ Loadout Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Mr. Kyle Edwards represented the Permittee during today's inspection.

Inspector's Signature:

Pete Hess. Inspector ID Number: 46 **Date**

Thursday, July



Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Thursday, July 08, 2010

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		\checkmark	
2.	Signs and Markers	✓			
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V		✓	
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓		~	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.a	a Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	V		✓	
21.	Bonding and Insurance	V		V	
22.	Other	✓		V	

Permit Number: C0070045
Inspection Type: COMPLETE

Inspection Date: Thursday, July 08, 2010

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit issued by the State of Utah is in effect until September 1, 2014. The NOI Air Quality Approval Order was renewed on January 5, 2009. The Division needs to modify the Special Permit Condition which is listed on attachment "A" of the current State permit which requires the electronic quarterly submittal of water monitoring data. This site has one ground water monitoring point, which is a well on the east side of the permit area. The water monitoring requirement established within the MRP only requires four quarterly samples during the first year of operation and four during the first year of reclamation of the site. The Permittee met the initial requirement on September 23, 2009, and notification of this was sent to the Division on November 30, 2009. No other water monitoring has occurred since, which is in accordance with the approved plan.

3. Topsoil

The east side topsoil pile was inspected and some coal fines were observed on the berm, and in the retention ditch surrounding the pile. No fines were observed on the pile itself. The stored soil has a surface crust, which seems to allow any wind borne fines to be blown off and away from the storage pile. The issue was discussed with Mr. Edwards. The Division suggested two possible ways to prevent a possible future compliance action; 1) install a "snow" fence on the west side of the topsoil pile to knock down the fines before they reach the pile, or 2) re-locate the pile to a spot where no coal storage exists on the west side of the storage location. Mr. Edwards agreed to discuss this with Ms. Gina Rau, Environmental Manager for the Permittee. Topsoil storage location signs are in place at both the east and west pile locations.

4.a Hydrologic Balance: Diversions

the 18 inch CMP reporting to ditch E-3. Plate 7-2, Site Watershed and Drainage Map will be updated accordingly, (See R645-301-722.500). The Permittee was instructed to submit both proposed changes to the Division as a modification to the Chapter 7 information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Mr. Edwards conducted the second quarter impoundment inspections for the east and west ponds on June 2, 2010. No signs of instability or other hazards were noted with either of the two incised ponds. As observed this day, only the west pond contained a small amount of water. No problems were identified.

9. Protection of Fish, Wildlife and Related Environmental Issues

The Permittee, through Dr. Patrick Collins of Mt. Nebo Scientific, conducted four burrowing owl surveys during June of 2010. No owls were observed during the two morning and two evening surveys. A final report is pending for submittal in the Permittee's 2010 Annual Report.

Permit Number: C0070045
Inspection Type: COMPLETE

Inspection Date: Thursday, July 08, 2010

Page 4 of 4

13. Revegetation

The Permittee has not conducted any additional seeding on the two topsoil piles since the June application made to the lower half of those piles. Mr. Edwards is waiting to determine the results of those initial applications.

20. Air Quality Permit

The current air quality Approval Order, DAQE-AN0129520006-09 was renewed on January 5, 2009. The amount of permitted throughput is 1.5 MTP rolling 12 month period. The required speed limit within the permit boundary is 10 MPH. An application of water to the operational haul roads was still visible.

21. Bonding and Insurance

The current policy period for the general liability insurance coverage remains in effect through October 1, 2010. There are no explosive or detonator storage magazines on site.

22. Other

The Division completed its review of the 2009 Annual Report information for the COVOL site on February 25, 2010.